

Asbestos Label Register

Inspection date: / /

This form is to be completed with reference to the **Division 5 Asbestos Audit Report** dated: 28/02/2017

Name and address of DET Workplace: Dhurringile PS, 605 Langham Rd, Dhurringile, 3610

Inspected by: Lisa Wilson, Principal

Updated checklist signed off by: Lisa Wilson, Principal

Asbestos Co-ordinator and

Health and Safety Representative

Building	Number of labels installed	Current Condition of Asbestos Labels	Action Required	Action Undertaken	Date
A	1	Good	nil	asbestos has been removed	5/05/2018
store	1	Good	nil	asbestos has been removed	5/05/2018