

# Asbestos Register

Inspection date: / /

This form is to be completed with reference to the Division 5 Asbestos Audit Report dated: 28th February 2017

Name and address of DET workplace: Dhurringile Primary School, 605 Langham Rd, Dhurringile, 3610

Inspection conducted by: Lisa Wilson, Principal

Updated Register signed off by: Lisa Wilson, Principal

Asbestos Coordinator and

Health and Safety Representative

Building / Site Location	Action Rating	SAMS Room Number/s	Room Description	Asbestos Containing Materials (ACM) Description	Surface (e.g. ceilings, walls)	Condition of ACM at Audit	Current Condition of ACM	Further Action / Comment	Date of Removal of Asbestos Item/s	Re-inspection date
A	A3	1	passage	2. amphibole asbestos (e	cement sheet backing	Requires attention	Good	has been removed	5/05/2018	N/A
A	A4	1	passage	1. chrysotile	electrical backing board	Good	Good	has been removed	5/05/2018	N/A
A	A3	5	staff office	1. chrysotile	Kookaburra safe	Good	Good	has been removed	5/05/2018	N/A
A	A3	external	external eaves	3. crocidolite	cement sheet eaves	Good	Good	has been removed	5/05/2018	N/A
A	A3	external	external eaves	3. crocidolite	cement sheet upper eaves	Good	Good	has been removed	5/05/2018	N/A
store	A3	7	art store shelter shed	1. chrysotile	cement sheet walls	Requires attention	Good	has been removed	5/05/2018	N/A
store	A4	7	art store shelter shed	1. chrysotile	cement sheet ceiling	Requires attention	Good	has been removed	5/05/2018	N/A